# **Customer Testimonial**



## Monolec® Ultra-Blend Engine Oil (8130)

Columbus Country Club - Columbus, Miss.

## Mowers

Extended oil drain intervals from 50 hours to 250 hours

### **Customer Profile**

Columbus Country Club is a scenic, well maintained 18-hole, 6,410 yd. golf course located in Columbus, Mississippi.

### **Application**

The golf course uses an array of different equipment used to maintain the grounds. Some of which are Jacobsen fairway greens mowers and Kubota tractors.

## Challenge

Jay Strickland, golf course superintendent, was interested in an engine oil that would meet and exceed manufacturer's requirements. He was also interested in extending oil drain intervals.

#### LE Solution

The local LE lubrication consultant recommended Monolec® Ultra-Blend Engine Oil (8130), which is used for heavy-duty, long-drain service in diesel and gasoline engines. It is effective during start-up cranking at low temperatures. It exceeds requirements for Mack, Detroit Diesel, Ford and General Motors.

#### Results

While using a commercial grade engine oil, the maintenance department would change oil at 50 hours. At the 50-hour drain interval, the commercial engine oil was visibly dark and dirty. Since the conversion to Monolec 8130, the oil drain intervals are now over 250 hours and the oil still looks good. Lamar Johnson, lead mechanic, feels as though he can easily go 300 hours on the drain intervals. That is five times less oil to dispose of and five times less oil consumed, with less downtime.





#### **Other Products Used**

- Nutrigent Industrial Cleaner (2100)
- L-X® Heavy-Duty Chemical Supplement (2300)
- Low Tox® Hydraulic Oil (6602)

Thank you to Jay Strickland, golf course superintendent, Lamar Johnson, lead mechanic, and to the local LE lubrication consultant, for providing the information used in this report.





 $Monolec^{\circledast}, L\text{-}X^{\circledast} \text{ and Low Tox}^{\circledast} \text{ are registered trademarks of Lubrication Engineers, Inc.}$ 

Based on actual user experience. Individual results may vary. Not intended to supersede manufacturer specifications

SIC 7997 LI70454 01-02





