## SET DESCRIPTION OF THE PROPERTY OF THE PROPERT

## HIGH-TEMP GREASE ENDS BEARING FAILURES IN BRICK PLANT KILN CARS

While regreasing its kiln car bearings monthly, a brick plant was still experiencing failures.

After switching to LE's Almasol® High Temp Lubricant, grease intervals have doubled, and bearing failures have been eliminated.



CONTACT US TO GET RESULTS LIKE THESE

